

See overleaf for more single seaters


Motor Pinion

fitted to all vehicles

from February 1992

Motor Pinion


L.7085



| List of Parts | | | | | | | | |
|--------------------------------------|----------------------|--------------------------------------|--------|--------------------------------------|--|--|--|--|
| Ref. No. | ltem | Ref. No. | Item | Ref. No. | ltem | | | |
| W.1439 W.2051 W.2052 W.2189 | Guide Blade Assembly | L.7085 M.2055 M.2985 | Pinion | S.9746 S.9747 S.9900 S.9901 | Front Tyre Rear Tyre Front Hub Rear Hub | | | |
| L.5174 L.5175 L.5176 | BodyUnderpanAerofoil | S.2483 S.9536 S.9706 S.9707 | Axle | 02545 05192 05967 13402 | Front Axle Spacer | | | |



TYLER, DUNLOP



| List of Parts | | | | | | | | |
|--------------------------------------|----------------------|--------------------------------------|--|--------------------------------------|--|--|--|--|
| Ref. No. | ltem | Ref. No. | Item | Ref. No. | Item | | | |
| W.1439 W.2051 W.2052 W.2190 | Guide Blade Assembly | M.2055 | Pinion Motor with Pinion and Harness Eyelet | S.9746 S.9747 S.9900 S.9901 | Front Tyre Rear Tyre Front Hub Rear Hub | | | |
| L.5183 L.5184 L.5185 | BodyUnderpanAerofoil | S.2483 S.9536 S.9706 S.9707 | Axle | 02545 05192 05967 13402 | Front Axle Spacer | | | |

Motor Pinion L.7085

fitted to all vehicles from February 1992

Replaces Motor Pinion 8 01796